

ship June 10

Work Order ID 146735

146735

Page 1

Friday, May 20, 2016 4:14:22 PM

Item ID: D407-559-115 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: 206L Series/407 Bearpaws - Run-on Landing Wearplate Compatible
 Start Date: 5/24/2016 Start Qty: 2.00 ***2*** Cust Item ID:
 Required Date: 6/10/2016 Req'd Qty: 2.00 ***2*** Customer:
 Reference:

Approvals: Process Plan: dm Date: 6/05/24 Tooling: _____ Date: _____ Run Start ***NR1***
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
DSI 9624	REV A								
100	Document Control	0.00							
100	DOCUMENT CONTROL								
DC	Memo	0.00							
Doc.Control -USB or Paperwork	Photocopy blue file and type labels per PPP D407-559-115 CHG001								
151	Pick Kit	0.00							
151									
Packaging	Memo	0.00							
Packaging									
160	QC4- 100% Inspect kits for completeness	0.00							
160									
QC	Memo	0.00							
Quality Control									

AUG 03 2016
MAY 30 2016

2x DAS 28 9-89 AUG 09 2016

2x DAS 26 9-89 AUG 05 2016
DAS 27 9-89

2x DAS 28 9-89 AUG 09 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By _____ Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
		OTHER : _____			

Friday, May 20, 2016 4:14:22 PM

146735

N900040100

Setup Start *NS1*

Stop *NS2*

Start Date: 5/24/2016 **Start Qty:** 2.00 ***2***

Cust Item ID:

Required Date: 6/10/2016 **Req'd Qty:** 2.00 ***~***

Customer:

Reference:

Approvals: _____ **Process Plan:** _____ **Date:** _____ **Tooling:** _____ **Date:** _____

Run Start *NR1*

QC: _____ **Date:** _____ **SPC (Y/N):** _____ **Date:** _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

170	Identify as per dwg & Stock Location:_____	0.00
-----	--	------

170

Packaging

Packaging

Memo

fs 14 21
Sch 2

0.00

Shirley

161810

180	QC21- Final Inspection - Work Order Release	0.00
-----	---	------

180

QC

Quality Control

Memo

0.00

16/8/9 JJ

dm 16/08/09

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐	OTHER : ☐			

Picklist Print

Friday, May 20, 2016 4:14:27 PM

Page 1

Work Order ID: 146735

146735

Parent Item: D407-559-115

D407-559-115

Parent Item Name: 206L Series/407 Bearpaws - Run-on Landing Wearplate Compatible

Start Date: 5/24/2016

Required Date: 6/10/2016

Start Qty: 2.00

Required Qty: 2.00

Comments: IPP REV:A NEW ISSUE 12-07-23 JLM VERIFIED BY:DD

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2274 *D2274* Radius Block		Manufactured	No				Each	390.0000	12 (24) **	MI47530			DAS 26 9-89 DAS 27 9-89
DAS 28 9-89 <u>Location</u> FG 12 86855 12 ST006 378 144391 378													
D2529 *D2529* Washer		Manufactured	No				Each	523.0000	12 (24) **	B147569			DAS 26 9-89 DAS 27 9-89
DAS 28 9-89 <u>Location</u> ST008 523 143819 273 145269 250													
D2432-3 *D2432-3* 206 (24") Bearpaw		Manufactured	No				Each	1.0000	2 (4) **	147447			DAS 26 9-89 DAS 27 9-89
DAS 28 9-89 <u>Location</u> ST454a 1 139891 1													
D4011-1 *D4011-1* Clamp, Short		Manufactured	No				Each	141.0000	6 12 **	12x			DAS 26 9-89 DAS 27 9-89
DAS 28 9-89 <u>Location</u> ST544 141 145016 141													

AUG 05 2016

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QS1042) Approval _____	
Description Work Order Deviation		Disposition		Completed By _____	
				Lead hand / Supervisor Approval Verification _____	
				QC / QA Coordinator Approval _____	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					

Picklist Print

Friday, May 20, 2016 4:14:27 PM

Work Order ID: 146735

146735

Parent Item: D407-559-115

D407-559-115

Parent Item Name: 206L Series/407 Bearpaws - Run-on Landing Wearplate Compatible

Start Date: 5/24/2016

Required Date: 6/10/2016

Start Qty: 2.00

Required Qty: 2.00

D4012-1

Manufactured No

Each

49.0000

6 12

D4012-1

Cushion

**

Ex B148908

DAS 26 9-89
DAS 27 9-89

Location

Loc Qty

Loc Code

FG

5

133458

5

ST545

44

144666

44

DAS 28 9-89

AN4-20A

Purchased No

Each

149.0000

12 (24)

AN4-20A

Bolt

**

m134943

DAS 26 9-89
DAS 27 9-89

Location

Loc Qty

Loc Code

GA

24

m116419

24

over003

60

m134039

60

ST343

65

m133694

27

m134634

38

DAS 28 9-89

NAS1149D0463J

Purchased No

Each

3,255.000

12 (24)

NAS1149D0463.J

WASHER

**

m134943

DAS 26 9-89
DAS 27 9-89

Location

Loc Qty

Loc Code

GA

146

M132035

21

M134508

125

ST260a

2600

M134754

2600

ST263

509

M134634

509

DAS 28 9-89

AUG 05 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					

Picklist Print

Friday, May 20, 2016 4:14:27 PM

Page 3

Work Order ID: 146735

146735

Parent Item: D407-559-115

D407-559-115

Parent Item Name: 206L Series/407 Bearpaws - Run-on Landing Wearplate Compatible

Start Date: 5/24/2016

Required Date: 6/10/2016

Start Qty: 2.00

Required Qty: 2.00

MS21042L4

Purchased

No

Each

2,035.000

12

(24)

MS21042L4

Locknut

**

~~m135327~~

m135127

DAS
26
9-89

DAS
27
9-89

AUG 05 2016

DAS
28
9-89

Location

Loc Qty

Loc Code

GA	187	
m133769	187	
OVER007	1500	
m134676	500	
m134762	1000	
ST303	251	
m134606	251	
ST305	97	
m130922	97	

Friday, May 20, 2016 4:14:27 PM

Shop Packet Print

Page 3

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS <table style="width:100%; border: none;"> <tr> <td style="border: none;">Skid-tube ☐</td> <td style="border: none;">Cross tube ☐</td> <td style="border: none;">Water Jet ☐</td> <td style="border: none;">Engineering ☐</td> </tr> <tr> <td style="border: none;">Machining ☐</td> <td style="border: none;">Small Fab ☐</td> <td style="border: none;">Prod. Eng. Coord. ☐</td> <td style="border: none;">Quality ☐</td> </tr> <tr> <td style="border: none;">Thermoforming ☐</td> <td style="border: none;">Finishing ☐</td> <td style="border: none;">Rec/Store/Packaging ☐</td> <td style="border: none;">Other ☐</td> </tr> <tr> <td style="border: none;">Large Fab ☐</td> <td style="border: none;">Composite ☐</td> <td style="border: none;">Supplier ☐</td> <td style="border: none;"></td> </tr> </table>						Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐																						
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐																						
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐																						
Large Fab ☐	Composite ☐	Supplier ☐																							
Date :		Step #:		QTY Effective :			MRB (QS1042) Approval																		
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval																	
Root Cause		FAULT CATEGORY																							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐				Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐				Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐				Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐											
		OTHER : _____																							

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS D206-559 Rev. L AND INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA-D206-559 REV. 3

REF CANADIAN STC: SH92-17

REF FAA STC: SH1031NE

REF LBA STC: 0796/3034

REF JCAB STC: STC-90-TYO

REF BRAZIL STC: 2010S10-08

1.0 PURPOSE

The purpose of this Dart Service Instruction is to add the D407-559-115 Bearpaw Kit to this approval. The D407-559-115 Bearpaw Kit is designed to be compatible with D206-642-311/-312/-313/-314/-411/-412/-413/-414 Skidtubes equipped with D206-642-XXX Run-On Landing Wearplates. The D407-559-115 Bearpaw Kit is also compatible with the D206-642-XXX Skidtubes equipped with standard wearplates/wearshoes.

2.0 INSTALLATION

To install D407-559-115 Bearpaw Kit on Dart D206-642-XXX Skidtubes equipped with D206-642-XXX Run-On Landing Wearplates refer to Figures 1 & 2 of this Service Instruction as well as the following:

- 2.1 Jack up the aircraft and ensure the skidtubes are serviceable in accordance with ICA-D206-642.
- 2.2 Position D2432-3 Bearpaw on the aft end of each skidtube so that the bearpaw clamps are located on either side of the aft saddle as shown in Figure 1a - 1c of this Service Instruction. The bearpaws should be installed over the run-on landing wearplates.
- 2.3 Attach the D4011-1 Clamps with D4012-1 Cushions using hardware shown in Figure 2 of this Service Instruction. Additional AN960JD416 (or NAS1149D0463J) washers may be installed under the nuts to ensure 1.5-4 threads in safety on the bolts. Although not generally necessary, it is also acceptable to replace the AN4-20A bolts with longer or shorter AN4 bolts, if required.

CAUTION: The torque on the nuts should be limited to 20 in-lb (2.3 Nm)

- 2.4 Lower the aircraft.
- 2.5 Update the aircraft log book to indicate installation of the D407-559-115 Bearpaw Kit and adjust the empty weight and balance record for the rotorcraft with the information given in section 5.0 of this service instruction.

3.0 MAINTENANCE


The D407-559-115 Bearpaw Kit should be maintained in accordance with ICA-D206-559.

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01


APPROVED
[Signature]
BY: D. SHEPHERD (DE # 02)

DATE: 12.07.05
CERT. NO.: SH92-17
ISSUE NO.: 7


A	NEW ISSUE	AP	12.07.05
REV.	DESCRIPTION	BY	DATE
DESIGN	AP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	AP		
CHECKED	<i>[Signature]</i>	DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9624	SHEET 1 OF 4
APPROVED	<i>[Signature]</i>	TITLE	SCALE
DE APPR.	<i>[Signature]</i>	BEARPAW INSTALLATION	NTS
DATE	12.07.05	COPYRIGHT © 2012 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	



**Figure 1a - Bearpaw Location
(Top View)**



**Figure 1b - Bearpaw Installation (Side View)
(Installed on D206-642-311/-312/-313/-314 Skidtubes)**



**Figure 1c - Bearpaw Installation (Side View)
(Installed on D206-642-411/-412/-413/-414 Skidtubes)**

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED
BY: *[Signature]*
D. SHEPHERD (DE # 02)

DATE: 12.07.05
CERT. NO.: SH92-17
ISSUE NO.: 7

DESIGN	AP
DRAWN	AP
CHECKED	<i>[Signature]</i>
MFG. APPR.	N/A
APPROVED	<i>[Signature]</i>
DE APPR.	<i>[Signature]</i>
DATE	12.07.05

DART AEROSPACE LTD
HAWKESBURY, ONTARIO, CANADA

DRAWING NO.	REV. A
DSI 9624	SHEET 2 OF 4
TITLE	SCALE
BEARPAW INSTALLATION	NTS

COPYRIGHT © 2012 BY DART AEROSPACE LTD
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS
NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT
WRITTEN PERMISSION FROM DART AEROSPACE LTD.




Figure 2 - D4011-1 Clamp Installation

4.0 PARTS LIST

QTY -115	PART NUMBER	DESCRIPTION
	D407-559-115	BEARPAW INSTALLATION
12	D2274	RADIUS BLOCK
12	D2529	WASHER
2	D2432-3	BEARPAW
6	D4011-1	CLAMP
6	D4012-1	CUSHION
12	AN4-20A	BOLT
12	AN960JD416	WASHER (NAS1149D0463J)
12	MS21042L4	NUT

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED
BY: 
D. SHEPHERD (DE # 02)
DATE: 12.07.05
CERT. NO.: SH92-17
ISSUE NO.: 7

DESIGN	AP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	AP		
CHECKED		DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9624	SHEET 3 OF 4
APPROVED		TITLE	SCALE
DE APPR.		BEARPAW INSTALLATION	NTS
DATE	12.07.05	COPYRIGHT © 2012 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

5.0 WEIGHT AND BALANCE

INSTALLATION	WEIGHT	LATERAL		LONGITUDINAL	
		ARM	MOMENT	ARM	MOMENT
D407-559-115 Bearpaw installation (Bell 407 High Gear)	13.9 lb 6.30 kg	0.0 in 0.0 m	0.0 in-lb 0.0 m-kg	148 in 3.76 m	2057 in-lb 23.69 m-kg
D407-559-115 Bearpaw installation (Bell 206L/407 Low Gear)	13.9 lb 6.30 kg	0.0 in 0.0 m	0.0 in-lb 0.0 m-kg	149 in 3.78 m	2071 in-lb 23.81 m-kg
D407-559-115 Bearpaw installation (Bell 206 L High Gear)	13.9 lb 6.30 kg	0.0 in 0.0 m	0.0 in-lb 0.0 m-kg	157 in 3.99 m	2182 in-lb 25.14 m-kg

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED

BY: 
D. SHEPHERD (DE # 02)

DATE: 12.07.05
CERT. NO.: SH92-17
ISSUE NO.: 7

DESIGN	AP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
DRAWN	AP	
CHECKED		DRAWING NO. REV. A
MFG. APPR.	N/A	DSI 9624 SHEET 4 OF 4
APPROVED		TITLE SCALE
DE APPR.		BEARPAW INSTALLATION NTS
DATE	12.07.05	COPYRIGHT © 2012 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

REF only

DAS
28
9-89




Figure 2 - D4011-1 Clamp Installation

4.0 PARTS LIST

QTY -115	PART NUMBER	DESCRIPTION
	D407-559-115	BEARPAW INSTALLATION
12	D2274	RADIUS BLOCK
12	D2529	WASHER
2	D2432-3	BEARPAW
6	D4011-1	CLAMP
6	D4012-1	CUSHION
12	AN4-20A	BOLT
12	AN960JD416	WASHER (NAS1149D0463J)
12	MS21042L4	NUT

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED

BY:
D. SHEPHERD (DE # 02)

DATE: 12.07.05
CERT. NO.: SH92-17
ISSUE NO.: 7

DESIGN	AP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	AP		
CHECKED	q	DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9624	SHEET 3 OF 4
APPROVED		TITLE	SCALE
DE APPR.		BEARPAW INSTALLATION	NTS
DATE	12.07.05	COPYRIGHT © 2012 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

[illegible]

Change Record

PAGE 1 OF 1

Part Number: D407-559-115

Description: BEARPAW INSTALLATION

[illegible]